

PARTS LIST

No.	Description	No.	Description
1	Inverted screw	11	Speed Button
2	chuck	12	Shell
3	Torque sleeve	13	Tapping Screw
4	Gearbox	14	Battery Pack
5	Motor Gear	15	Switch Assembly
6	Machine screw	16	Belt Clip
7	Motor	17	Machine screw
8	tuning fork	18	Magnet Ring
9	Handspike	19	Heat-shrink Tube
10	Variable Steel		

ASSEMBLY DIAGRAM

