

PARTS LIST

| No. | Description    | No. | Description      |
|-----|----------------|-----|------------------|
| 1   | Inverted screw | 10  | Speed Button     |
| 2   | chuck          | 11  | Shell            |
| 3   | Gearbox        | 12  | Tapping Screw    |
| 4   | Motor Gear     | 13  | Battery Pack     |
| 5   | Machine screw  | 14  | Switch Assembly  |
| 6   | Motor          | 15  | Belt Clip        |
| 7   | tuning fork    | 16  | Machine screw    |
| 8   | Handspike      | 17  | Magnet Ring      |
| 9   | Variable Steel | 18  | Heat-shrink Tube |

### ASSEMBLY DIAGRAM

