

PARTS LIST

No.	Description	No.	Description
1	tapping screws	11	ring gear
2	Rubber sleeve	12	motor shaft gear
3	Al head shell	13	deep groove ball bearing
4	Output shaft sleeve	14	Motor
5	Output shaft	15	Back Cover
6	gasket	16	Handspike
7	gasket	17	Switch Assembly
8_1	impact block	18	Shell
8_2	steel ball	19	Tapping Screw
8_3	gasket	20	PCB stents assembly
8_4	spring	21	Transparent Cover
8_5	Central output shaft	22	Battery pack (87259 not include)
8_6	steel ball	23	Machine screw
9	Gear pin	24	Belt clip
10	planet gear	25	Nameplate

ASSEMBLY DIAGRAM

